

OPERATOR INTERFACE PRODUCTS APPLICATION NOTE

Subject: 9457/9407 Touchscreen Installing for Windows 95 Date: 9/24/96 Name: Irvin Hayes Jr Page: 10f 2 AN# 1047A

Description: Installing Touchscreen Drivers in Windows 95 for the 9457/9407

Installation

- 1. Run the T5Setup.EXE file from the Touchscreen installation diskette.
- 2. Select the directory you want to install the drivers.
- 3. You will see the Select Touchscreen menu come up, you should select Unitouch Serial.
- 4. Select the Group name you would like to install the Touchscreen Icons in.
- 5. From the Configure Window select the Com Port you have connected the touchscreen to. Leave the rest of the settings as default.
- 6. Now Shutdown and Restart your computer.
- 7. Select the Touchscreen Control icon from the group you selected in step 4.
- 8. Select the Calibrate button from the toolbar and follow the on screen instructions for calibration. After this is complete your touchscreen should be in full operation.

Disabling or Uninstalling the Driver

Temporarily Disabling the Driver

If you need to temporarily prevent T5driver from loading, you can do so using the Windows 95 Device Manager.

- In the Control Panel, double click the System icon, then click the Device Manager tab.
- Double click the Mouse device icon to open up the mouse device tree.
- Click on the touchscreen device to select it, then click the Properties button.
- Uncheck the Original Configuration checkbox on the General property page.

To re-enable the driver later, use the same procedure to check the Original Configuration checkbox on the driver's General property page.



OPERATOR INTERFACE PRODUCTS APPLICATION NOTE

Subject: 9457/9407 Touchscreen Installing for Windows 95 Date: 9/24/96 Name: Irvin Hayes Jr Page: 20f 2 AN# 1047A

Description: Installing Touchscreen Drivers in Windows 95 for the 9457/9407

Permanently Uninstalling the Driver

The simplest way to uninstall the driver is to use the Windows 95 Device Manager to delete it:

- In the Control Panel, double click the System icon, then click the Device Manager tab.
- Double click the Mouse device icon to open up the mouse device tree.
- Click on the touchscreen device to select it, then click the Remove button. This removes the device driver.
- If you wish, you can now use Windows Explorer or some other method to delete the control program and its help file.